


PROTECT YOUR FAMILY THIS WINTER

Heavy snow and ice can damage natural gas meters and create hazardous leaks, and blocked vents can cause Carbon Monoxide (CO) poisoning.

Here are some ways you can protect your family & stay safe.



Be aware of overhead snow and ice above your meter

Don't bury your meter and vents

Allow vents to exhaust properly to prevent CO poisoning

Maintain a clear path to meter for emergency access

Keep meters free of snow and ice by using a broom and not a shovel

If you suspect a natural gas leak or CO poisoning, leave the area immediately and call 911 or WG+E Dispatch at 413-572-000.

If you have ice on your meter, call WG+E Dispatch at 413-572-0000 and we'll send someone to safely remove it.

WG+E